













1965 Chevrolet Corsa Corvair Convertible.

Originally purchased, used, in '65 by my father in Hayward, CA. It's been a Bay Area car ever since. This was the car in which my mom drove me, my brother, and sister around town. Without doubt, it holds significant sentimental value for me. As we got older it was driven less and less, until my sister was allowed to take it over in high school. Over time, and as we acquired newer cars, the Corvair became a forgotten fixture in the garage, mostly because it was near impossible to find a reliable mechanic.

Cut to 2015. I was working in San Francisco at an advertising firm that had just won the Chevrolet account. We celebrated the win by inviting several car clubs to show off their Chevys in our parking lot while we downed beers. I started to ask around if anyone had ever worked on Corvairs...nobody had but this one guy from one of the car clubs looked up from his hot dog and said he would give it a shot. A week later he showed up with a flatbed truck at my parents' house and hauled it away. A few months passed and a big check later, we were back in business. He loved rebuilding that Corvair so much, he went on to buy his own.

I was fired up to take over the newly rebuilt Corvair. I had three very young children at the time and quickly realized that it wasn't going to get much of my attention. I drove it to work sometimes, I'd pick my mom up for Sunday drives, but mostly, it has sat in my driveway under a tarp. I love that car, and I didn't think I would ever part with it. My favorite thing was to take it out in the summer months, with the top down, and cruise for hours through the quiet country roads behind my parents' house. During those isolated months of the Pandemic, that's what our family looked forward to on warm evenings. Top down, my wife in the front, three kids with no seat belts and the dog in the back, the wind blowing our hair out of control, the sunset warming our cold faces, and feeling grateful for our health and each other.

One day, I must have pushed it too much and started hearing some horrible sounds, I knew instantly the motor was in trouble. We were able to limp home, but it's been sitting ever since. As much as I would love to hold onto it forever, I'd rather it go to someone that will love it enough to get it rolling again. I've spent a lot of money getting it to this point, and would have done it differently in hindsight especially after finding the Corvair club. I have no idea how to price it, and am hoping you can help me find a loving forever home for it.

ps. It doesn't leak.

-Michael Chamorro
middlechamorro@gmail
415-310-2482



LUKE RIZZUTO

General Contractor

License #364538

PH: 408.353.3505

16205 Redwood Lodge Road
Los Gatos, CA 95033

SUBMITTED TO:

Name _____

Address _____

Phone _____ Fax _____

DATE	DESCRIPTION	PRICE
12/13/10	INSTALL HEATER DUCTING & REPAIR	6 HRS
12/14/10	FINISH HEATER DUCTING INSTALL REAR SPRING & SHOCK	4 HRS
12/15/10	INSTALL EXHAUST SYSTEM, FRONT SHOCKS & RUST TREATING	6 HRS
12/17/10	RUST TREATING	2 HRS
12/18/10	ASSEMBLE CARPET & REAR SIDE PANELS	4 HRS
12/19/10	REPAIR ELECTRICAL & FRONT CARPET & WINDOW FELT	4 HRS
12/26/10	INSTALL REAR SEAT	3 HRS
	" REAR VENT	2 HRS
12/28/10	REBUILD 4 CARBS, START & TUNE	6 HRS
12/29/10		2 HRS
1/4/11	PREP FOR CONVERTIBLE TOP	4 HRS
1/26/11	INSTALL DOOR PANELS & WEATHER STRIPPING	4 HRS
1/27/11	FINISH SEATS & CARPET	3 HRS
1/28/11	REPAIR & REPLACE ALL LIGHTS	2 HRS
		2 HRS
2/3/11	MISC. DETAILING	3 HRS
2/4/11	INSTALL RUBBER BOOTS	2 HRS
	" TRIM	
2/5/11	" MISC. ITEMS	
2/6/11		
	TOTAL	59 HRS

GRAND TOTAL \$ 3540.00

SUBMITTED BY:

CLARK'S CORVAIR PARTS, INC.
 Route 2, 400 Mohawk Trail
 Shelburne Falls, MA 01370
 (413)625-9776

YOUR CUSTOMER # IS: B6673

ORDER #: 653928

DATE ENTERED: 11/30/2010
 DATE SHIPPED: 12/03/2010

SHIP VIA: UPS
 PAYMENT: Visa

NAME: MIKE CHAMORRO
 ADDRESS: 720 CALIFORNIA ST
 SAN FRANCISCO, CA 94108

SHIP TO: MIKE CHAMORRO
 ADDRESS: c/o LUKE RIZZUTO (408)590-2946
 16205 REDWOOD LODGE RD
 LOS GATOS, CA 95033

DAY PHONE: (415)676-4559

PART #	QTY	STAT	DESCRIPTION	CORE	EACH	TOTAL
C6195	1	OK	I UPHOLSTERY-FULL SET-65 CT		452.20	452.20
C6331	1	OK	I FT DOOR PANEL-65 CP & CT LEFT-COMP		86.85	86.85
C6332	1	OK	I FT DOOR PANEL-65 CP & CT RIGHT-COM		86.85	86.85
C6281	1	OK	I QTR WINDOW PANEL-65 CT LEFT		39.30	39.30
C6282	1	OK	I QTR WINDOW PANEL-65 CT RIGHT		39.30	39.30
C1479BX	1	OK	I CARPET 65-66 CONVERTIBLEX		146.65	146.65
C10632	1	OK	65-69 ULTIMATE TOP KIT WITH HD BLA		451.05	451.05
C7645	1	OK	65-69 CT TOP WEATHERSTRIPS-SET 6-A		281.70	281.70
C7929	1	OK	65-69 CT TOP FT BOW W/STRIP-EXACT		71.50	71.50
C3755	2	OK	RETAINER-EA-65-69 CT WEATHERSTRIP		1.05	2.10
C3842	2	OK	RUBBER FLAP-65-69 CT		3.50	7.00
C6388	1	OK	I TOP BOOT-65-69 CT BLACK(HB)		183.90	183.90
C10653HB	2	OK	I SUNVISOR COMPLETE-65 CT MONZA/CORS		74.30	148.60
C93	2	OK	I CONV'T SUNVISOR ANTI-RATTLE		3.25	6.50
C7725	2	OK	I SUNVISOR BUSHING 65-69-EA		4.85	9.70
C10805	2	OK	I BUCKET SEAT CUSHION SET-60-66 LF O		113.95	227.90
C10586MF	1	OK	ULTIMATE HEATER KIT W/MOTOR&FAN-65		300.90	300.90
C2835	2	OK	65-69 REAR RED RYDER SHOCK-HD		45.50	91.00
C2834	2	OK	65-69 FT RED RYDER SHOCK-HD		41.25	82.50
C760CT	2	OK	COIL SPRG 65-69 STOCK REAR CONVNT-		53.80	107.60
C2416	1	OK	FT MOUNT ANTENNA		14.95	14.95
C862	1	OK	65-66 & 64-65 FC DIRECTIONAL SWITC		73.20	73.20
CU1860	1	OK	USED 65-66 CORSA HORN BUTTON (EXC		25.00	25.00
C6170	4	OK	3-PRONG SPINNER-1964-66 CHEVY WIRE		34.45	137.80
C98	1	OK	65-9 REAR SHIFT ROD BOOT-REPRO**ND		20.65	20.65
C98A	1	OK	65-9 CLUTCH CABLE BOOT-TRANS END-R		24.30	24.30
C100R	1	OK	61-69 ACCELERATOR BOOT IN ENGINE		11.40	11.40
C100X	1	OK	ACCELERATOR BOOT RETAINER		5.10	5.10
C540	1	OK	60-69 SHIFT COUPLER BOOT		7.00	7.00
C3016	1	OK	65-66 CORSA RUBBER SHIFT LEVER BAS		4.70	4.70
C8232	1	OK	SET OF 4 NUTS FOR CORSA SHIFTER FL		2.90	2.90
C4608	1	OK	SCREW-OS-REAR AIR EXHAUST GRILL-SE		2.90	2.90
C11103	1	OK	ULTIMATE EXHST KIT-65-9 140 W/WELD		562.15	562.15
C11582	1	OK	CHROME TAILPIPES-PAIR FOR WELDED D		39.05	39.05

Totals on next page

LUKE RIZZUTO
 General Contractor
 License #364538
 PH: 408.353.3505
 16205 Redwood Lodge Road
 Los Gatos, CA 95033



SUBMITTED TO:

Name _____
 Address _____
 Phone _____ Fax _____

ORDER # 653928

* CLARK KITS & MULTI KITS *

1	PART #	C11103	ULTIMATE EXHST KIT-65-9 140 W/WELDED	QTY	1
2	PAGE	3-1	TAILPIPE (WILL FIT 60-64 WITH 140HP EXC		2
3					3
4					4
5	LOCATION	PART #	QTY DESCRIPTION		5
6					6
7	B1F1	C369R	1 ✓ 140 LEFT EXHAUST MANIFOLD-LONGER ONE		7
8		C370R	1 ✓ 140 RIGHT EXHAUST MANIFOLD-SHORTER ONE		8
9		C370XA	2 ✓ 140 MANIFOLD KIT FOR C369RK/C370RK		9
10		C1159	1 ✓ 65 EXHAUST MANIFOLD CLAMP NUTS-SET 6		10
11	B1F1BS	C9052A	1 ✓ 140 DUAL EXHAUST INSTALL KIT-**(HANGERS,		11
12	B7L3	C10997	1 ✓ 140HP WELDED RIGHT SIDE MUFFLER		12
13		C10998	1 ✓ 140HP WELDED LEFT SIDE MUFFLER		13
14	B1F1MUF	KC256NR	1 ✓ INST NON-ORIGINAL 140 MUFFLERS W/WELDED		14
15					15
16					16
17					17
18					18
19					19
20					20
21					21
22					22
23					23
24					24

ORDER # 653928

* CLARK KITS & MULTI KITS *

1	PART #	C10632	65-69 ULTIMATE TOP KIT WITH HD BLACK TOP	QTY	1
2	PAGE	2-1			2
3					3
4					4
5	LOCATION	PART #	QTY DESCRIPTION		5
6					6
7	B1F1	C1710	2 ✓ CT TOP CHROME END		7
8		C2007	1 ✓ 5 OZ. TUBE OF GLUE-YELLOWISH		8
9		C3427	1 ✓ 65-69 CT WELL INSULATION PADDING		9
10		C3735	1 ✓ QT GLUE-NON FLAMMABLE		10
11		C4515	1 ✓ BLACK CONVERTIBLE TOP SIDE PADS - PAIR		11
12		C4523	1 ✓ 65-69 NON-ORIGINAL BLACK WELL		12
13		C6118	1 ✓ SPACERS-RUBBER CT TOP-SET 17		13
14		C6150	1 ✓ WATERPROOF BLACK CARDBOARD-CT TACK STRIP		14
15	B1F1HAL	C6541	1 ✓ HEAVY DUTY CT TOP-BLACK 65-69		15
16	B1F1	C6721	1 ✓ RUBBER TOP BOW SPACERS-SET 4		16
17		C7033	1 ✓ 1/2 PINT OF VINYL GLUE		17
18		C7527	1 ✓ SCREW-CT TOP CHROME ENDS-SET 2		18
19					19
20					20
21					21
22					22
23					23
24					24
25					25

ORDER # 653928

* CLARK KITS & MULTI KITS *

1	PART #	C10586MF	ULTIMATE HEATER KIT W/MOTOR&FAN-65-9 ALL	QTY	1
2	PAGE	1-1			2
3					3
4					4
5	LOCATION	PART #	QTY DESCRIPTION		5
6					6
7	B1F1	C203	2 ✓ THERMOSTAT SHROUD FOAM SEAL - L OR R		7
8		C204	1 ✓ THERMOSTAT SHROUD FOAM SEAL		8
9	B1F1PT	C386R	2 ✓ HOSE-HEATER- FABRIC (2 NEEDED)		9
10	B1F1	C387A	2 ✓ CLAMP FOR C387R/C3131R HOSE		10
11		C387R	1 ✓ FABRIC HOSE-OVAL-65-69 HEATER FAN TO FT*		11
12		C593X	4 ✓ ORIGINAL STYLE HEATER HOSE CLAMP		12
13	B1F1PT	C764	1 ✓ HOSE-FABRIC-65-69 SPECIAL OVAL FRESH AIR		13
14	B1F1	C837R	2 ✓ 65-69 HEATER HOSE STRAP		14
15		C2285	2 ✓ HEATER HOSE DUCT TO SHROUD SEAL		15
16		C2286A	1 ✓ TURBO RT SIDE HEATER HOSE DUCT TO SHD SL		16
17		C2418	2 ✓ MANIFOLD COLLAR-ALL ENGINES-EA		17
18		C2778	1 ✓ HEATER FAN BLADE		18
19		C3029	2 ✓ FRESH AIR HOSE CLAMP		19
20		C3150	1 ✓ DEFROSTER FLAP FOAM-65-69		20
21		C3233	1 ✓ HEATER DUCT FOAM-TOP PIECES 65-69		21
22		C3410	1 ✓ CARDBOARD-DEFROSTER DEFLECTORS 65-69		22
23		C3928	1 ✓ HI-VOLUME HEATER FAN MOTOR-61-69 (EXC		23
24		C4960	1 ✓ HEATER DUCT FRONT FOAM 65-69		24
25		C4961	1 ✓ HEATER DUCT REAR OUTLET FOAM 65-69		25
26		C4962	1 ✓ HEATER DUCT JOINT FOAM 65-69		26
27		C5567	1 ✓ SCREWS-HEATER MOTOR 61-69-SET 5		27
28	B1F1BS	C8281	1 ✓ HEATER HOSE "COLLAR"		28
29		C8405	1 ✓ TOE PANEL SEAL SET (2 PIECES)65-69		29
30					30
31					31
32					32
33					33
34					34
35					35
36					36
37					37
38					38
39					39
40					40
41					41
42					42
43					43
44					44
45					45
46					46
47					47
48					48
49					49
50					50
51					51
52					52
53					53
54					54
55					55
56					56

Orinda Classic Car center
 63 ORINDA WAY
 ORINDA, CA. 94563
 (925) 254-5454
 Writer: VP

INVOICE # 5047175

Service@orindaclassiccarcenter.com
 WWW.OCCC.SHOP
 BAR# BAR/ARD191519
 EPA# CAL0050068

MIKE CHAMORRO 44 STARK KNOLL PLACE OAKLAND, CA. 94618 Home: (415) 310-2482 Cell: 510 Work: 510	YEAR:: 1965 MAKE:/MODEL:: CHEVROLET CORVAIR CORS VIN:: 107675L122527 ENGINE: 164 CID	TRANS:/DRIVE:: MANUAL/ LICENSE:/STATE:: NKV909/ MILES IN/MILES OUT: 41113/
---	---	--

In: 9/16/2020 Out: 9/16/2020 Email: MIDDLECHAMORRO@ME.COM

AIR PRESSURE IN		AIR PRESSURE OUT		TREAD DEPTH	
PSI		PSI	PSI	PSI	/32"
PSI		PSI	PSI	PSI	/32"

VEHICLE ISSUE #1: DRIVE BELT NEEDS REPLACEMENT.			
TECH REPORT:			
PART: C5790	WRAPPED FAN BELT	1 @ \$40.05	\$40.05 NEW
LABOR: grs	REPLACE DRIVE BELT		\$125.00 LABOR
			Total for "DRIVE BELT NEEDS REPLACEMENT.": \$165.05
VEHICLE ISSUE #2: (CUSTOMER DECLINED)			
TECH REPORT: PERFORM DIAGNOSIS OF INOPERABLE WINDSHIELD WASHER SYSTEM.			
			*** CUSTOMER DECLINED THIS REPAIR AT THIS TIME ***
			Total for "": \$0.00
VEHICLE ISSUE #3: (CUSTOMER DECLINED)			
TECH REPORT: REPLACE TRANSMISSION MOUNTS COLLAPSED			
			*** CUSTOMER DECLINED THIS REPAIR AT THIS TIME ***
			Total for "": \$0.00
VEHICLE ISSUE #4: (CUSTOMER DECLINED)			
TECH REPORT: REVERSE LIGHTS ARE NON-OP			
			*** CUSTOMER DECLINED THIS REPAIR AT THIS TIME ***
			Total for "": \$0.00
VEHICLE ISSUE #5: (CUSTOMER DECLINED)			
TECH REPORT: PERFORM DIAGNOSIS RELATED TO RIVERS SIDE TAIL OUT.			
			*** CUSTOMER DECLINED THIS REPAIR AT THIS TIME ***
			Total for "": \$0.00
VEHICLE ISSUE #6: THANK YOU! WE APPRECIATE YOUR BUSINESS			

Warranty: From the date of delivery for a period of 6 months or 6,000 miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of \$25 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Labor/Jobs	\$3,507.30
	Parts	\$728.62
	Sublet	\$0.00
	Total Fees	\$41.75
	Subtotal	\$4,255.68
	Tax @ 9.75%	\$63.74
	Total	\$4,277.67
	Payments	\$4,341.41
	Balance	-\$63.74

Replaced parts may be requested by customer prior to vehicle pickup. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond our control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I acknowledge notice and oral approval of an increase in the original estimated price. I have read the above and acknowledge receipt of an estimate. CREDIT CARD CUSTOMERS: Cardmember agrees to perform the obligations set forth by the cardmember's agreement with the Issuer.

X _____ Date 1/14/2025

Orinda Classic Car center
 63 ORINDA WAY
 ORINDA, CA. 94563
 (925) 254-5454
 Writer: VP

INVOICE # 5047175

Service@orindaclassiccarcenter.com
 WWW.OCCC.SHOP
 BAR# BAR/ARD191519
 EPA# CAL0050068

MIKE CHAMORRO	YEAR::	1965	TRANS:/DRIVE::	MANUAL/
44 STARK KNOLL PLACE OAKLAND, CA. 94618	MAKE:/MODEL::	CHEVROLET CORVAIR CORS	LICENSE:/STATE::	NKV909/
Home: (415) 310-2482 Cell: 510	VIN::	107675L122527	MILES IN/MILES OUT:	41113/
Work: 510	ENGINE:	164 CID		

In: 9/16/2020 Out: 9/16/2020 Email: MIDDLECHAMORRO@ME.COM

TECH REPORT:			
LABOR:	****THANK YOU FOR ALLOWING ORINDA MOTORS INC. THE OPPORTUNITY TO SERVICE YOUR VEHICLE. WE KNOW YOU HAVE A CHOICE IN AUTOMOTIVE REPAIR, AND APPRECIATE YOUR TRUST IN US!	\$0.00	LABOR
Total for "THANK YOU! WE APPRECIATE YOUR BUSINESS": \$0.00			

VEHICLE ISSUE #7:			
TECH REPORT:			
LABOR:	REPLACE VOLTAGE REGULATOR, RECHECK CHARGING SYSTEM PERFORMANCE	\$112.00	LABOR
Total for "": \$112.00			

VEHICLE ISSUE #8:			
TECH REPORT:			
LABOR: grs	DRAIN OIL, REFILL WITH 20W50 AND A BOTTLE OF LUCAS	\$112.00	LABOR
Total for "": \$112.00			

VEHICLE ISSUE #9: REPLACE BATTERY AFTER FAILED LOAD TEST THIS DEALER IS REQUIRED BY LAW TO CHARGE A NONREFUNDABLE \$1 CALIFORNIA BATTERY FEE AND A REFUNDABLE DEPOSIT FOR EACH LEAD-ACID BATTERY PURCHASED			
TECH REPORT:			
PART: 36RPS	BATTERY	1 @ \$142.08	\$142.08 NEW
LABOR: grs	INSTALL NEW BATTERY AND SECURE BATTERY TO VEHICLE. INSTALL NEW BATTERY THAT FITS BATTERY TRAY AND HAS BATTERY POSTS IN CORRECT LOCATION. NEW BATTERY PASSES WITH 12.6 VOLTS AND 580 AMPS.		\$68.00 LABOR
Total for "REPLACE BATTERY AFTER FAILED LOAD TEST THIS DEALER IS REQUIRED BY LAW TO CHARGE A NONREFUNDABLE \$1 CALIFORNIA BATTERY FEE AND A REFUNDABLE DEPOSIT FOR EACH LEAD-ACID BATTERY PURCHASED": \$210.08			

VEHICLE ISSUE #10: PERFORM CYLINDER LEAK DOWN TEST FOR SMOKING.			
TECH REPORT: RECOMMEND VALVE JOB WITH NEW SEALS.			
PART: 2200-14	14MMX25	1 @ \$48.03	\$48.03 NEW
LABOR: grs	PERFORM CYLINDER LEAKDOWN TEST FOR ENGINE SMOKING. REMOVE SPARK PLUGS AND PERFORM CYLINDER LEAK DOWN TEST . CYLINDER TWO SPARK PLUG CAME OUT WITH THREADS ON IT AND WHEN SPARK PLUG WENT BACK IN IT WOULDN'T TIGHTEN . HELI COIL THREADS IN CYLINDER HEAD FOR CYLINDER TWO. PERFORM CYLINDER LEAK DOWN TEST AND IT WAS OK . CYLINDER #1) 25%		\$375.00 LABOR

Warranty: From the date of delivery for a period of 6 months or 6,000 miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of \$25 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Labor/Jobs	\$3,507.30
	Parts	\$728.62
	Sublet	\$0.00
	Total Fees	\$41.75
	Subtotal	\$4,255.68
	Tax @ 9.75%	\$63.74
	Total	\$4,277.67
	Payments	\$4,341.41
	Balance	-\$63.74

Replaced parts may be requested by customer prior to vehicle pickup. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond our control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I acknowledge notice and oral approval of an increase in the original estimated price. I have read the above and acknowledge receipt of an estimate. CREDIT CARD CUSTOMERS: Cardmember agrees to perform the obligations set forth by the cardmember's agreement with the Issuer.

X _____ Date 1/14/2025

Orinda Classic Car center
 63 ORINDA WAY
 ORINDA, CA. 94563
 (925) 254-5454
 Writer: VP

INVOICE # 5047175

Service@orindaclassiccarcenter.com
 WWW.OCCC.SHOP
 BAR# BAR/ARD191519
 EPA# CAL0050068

MIKE CHAMORRO	YEAR::	1965	TRANS:/DRIVE::	MANUAL/
44 STARK KNOLL PLACE OAKLAND, CA. 94618	MAKE:/MODEL::	CHEVROLET CORVAIR CORS	LICENSE:/STATE::	NKV909/
Home: (415) 310-2482 Cell: 510	VIN::	107675L122527	MILES IN/MILES OUT:	41113/
Work: 510	ENGINE:	164 CID		

In: 9/16/2020 Out: 9/16/2020 Email: MIDDLECHAMORRO@ME.COM

LEAKAGE AT RINGS / #2) 25% AT RINGS /#3) 20% AT RINGS / #4) 31% AT RINGS / #5)40% AT RINGS /#6) 15% AT RINGS . WITH THE SMALL LEAKAGE CONFIRMS THE CYLINDERS HEAD VALVE SEALS ARE CAUSING THE OIL ISSUE. NOTE: THE BATTERY IS DEAD WITH ONLY 125 AMPS AND 12 VOLTS . NEED TO REPLACE THE BATTERY .			
LABOR: grs	INSTALL HELI-COIL TO SPARK PLUG HOLE ON CYLINDER #2.	\$210.00	LABOR

Total for "PERFORM CYLINDER LEAK DOWN TEST FOR SMOKING.": \$633.03

VEHICLE ISSUE #11: CALIFORNIA REQUIRED TIRE PRESSURE TEST			
TECH REPORT:			
LABOR: grs	CALIFORNIA REQUIRED TIRE PRESSURE TEST. WE DO NOT CHARGE FOR THE PRESSURE TEST. CHECK AND INFLATE VEHICLE TIRES TO THE RECOMMENDED TIRE PRESSURE RATING. TIRE PRESSURE SETTING: FRONT - 30 PSI TIRE PRESSURE SETTING: REAR - 32 PSI SPARE TIRE SET TO (IF ACCESSIBLE) - PSI	\$0.00	LABOR
Total for "CALIFORNIA REQUIRED TIRE PRESSURE TEST": \$0.00			

VEHICLE ISSUE #12: (CUSTOMER DECLINED)			
TECH REPORT: WHEEL ALIGNMENT AFTER REPAIRS.			
*** CUSTOMER DECLINED THIS REPAIR AT THIS TIME ***			
Total for "": \$0.00			

VEHICLE ISSUE #13: (CUSTOMER DECLINED)			
TECH REPORT: REPLACE STABILIZER LINKS WITH BUSHINGS AND HARDWARE.			
*** CUSTOMER DECLINED THIS REPAIR AT THIS TIME ***			
Total for "": \$0.00			

VEHICLE ISSUE #14: (CUSTOMER DECLINED)			
TECH REPORT: REPLACE LEAKING SHIFTER SHAFT SEAL.			
*** CUSTOMER DECLINED THIS REPAIR AT THIS TIME ***			
Total for "": \$0.00			

VEHICLE ISSUE #15:			
TECH REPORT: ESTIMATE CARBURETOR OVERHAUL OR REPLACEMENT (4 CARBS) DUE TO LEAKS			
PART: EBAY	SET OF 4 CORVAIR 1965 140 HP PREMIUM REBUILT CARBURETORS	1 @ \$987.53	\$987.53 NEW
LABOR:	REMOVE ALL 4 CARBS, REPLACE WITH REMANUFACTURED UNITS. ADJUST AND CHECK EMISSIONS.		\$1,260.00 LABOR
Total for "": \$2,247.53			

Warranty: From the date of delivery for a period of 6 months or 6,000 miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of \$25 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Labor/Jobs	\$3,507.30
	Parts	\$728.62
	Sublet	\$0.00
	Total Fees	\$41.75
	Subtotal	\$4,255.68
	Tax @ 9.75%	\$63.74
	Total	\$4,277.67
	Payments	\$4,341.41
	Balance	-\$63.74

Replaced parts may be requested by customer prior to vehicle pickup. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond our control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I acknowledge notice and oral approval of an increase in the original estimated price. I have read the above and acknowledge receipt of an estimate. CREDIT CARD CUSTOMERS: Cardmember agrees to perform the obligations set forth by the cardmember's agreement with the Issuer.

X _____ Date 1/14/2025

Orinda Classic Car center
 63 ORINDA WAY
 ORINDA, CA. 94563
 (925) 254-5454
 Writer: VP

INVOICE # 5047175

Service@orindaclassiccarcenter.com
 WWW.OCCC.SHOP
 BAR# BAR/ARD191519
 EPA# CAL0050068

MIKE CHAMORRO	YEAR::	1965	TRANS:/DRIVE::	MANUAL/
44 STARK KNOLL PLACE OAKLAND, CA. 94618	MAKE:/MODEL::	CHEVROLET CORVAIR CORS	LICENSE:/STATE::	NKV909/
Home: (415) 310-2482 Cell: 510	VIN::	107675L122527	MILES IN/MILES OUT:	41113/
Work: 510	ENGINE:	164 CID		

In: 9/16/2020 Out: 9/16/2020 Email: MIDDLECHAMORRO@ME.COM

VEHICLE ISSUE #16: ACTIVE EXHAUST LEAKS AT MANIFOLD				
TECH REPORT: RECOMMEND REBUILD THE ENGINE DUE TO BURNING OIL AND CAMSHAFT ISSUES.				
PART: C8615	EXHAUST DONUTS SET OF 8	1 @ \$67.20	\$67.20	NEW
PART: C201	MOLDED RUBBER VALVE COVER GASKET	1 @ \$12.60	\$12.60	NEW
PART: C236X	PUSH ROD	1 @ \$28.18	\$28.18	NEW
PART: VR103T	VOLTAGE REGULATOR	1 @ \$59.95	\$59.95	NEW
PART: 20W-50	CHEVRON SUPREME MOTOR OIL/QT.	4 @ \$6.49	\$25.96	NEW
PART: 10001	OIL STABILIZER	1 @ \$29.67	\$29.67	NEW
LABOR: grs	REMOVE MUFFLERS AND EXHAUST MANIFOLDS TO INSTALL NEW SEALS . REMOVE DRIVER SIDE VALVE COVER ATTEMPT TO REMOVE EXHAUST TUBE AND FOUND THE EXHAUST TUBE WILL NOT COME OUT WITH OUT REMOVING CYLINDER HEAD. DURING INSPECTION FOUND BROKEN PUSH ROD CYLINDER #6 .		\$630.00	LABOR
LABOR: grs	REPLACE BROKEN PUSHROD AND ADJUST VALVES WITH ENGINE RUNNING 1/2 TURN PAST ZERO . NOTE :CYLINDER 6 CAMSHAFT LOBE IS WORN AND BARELY OPENING THE VALVE. ENGINE WILL REQUIRE REBUILD DUE TO BURNING OIL AND CAMSHAFT ISSUES. ENGINE SEEMS TO IDLE A LITTLE BETTER NOW THAT CYLINDER #6 IS WORKING NOW AT THIS TIME.		\$450.00	LABOR
LABOR: grs	CHANGE ENGINE OIL WITH 20/50 AND ADD LUCAS ENGINE STABILIZER ADDITIVE. AFTER OIL CHANGE NOTICED AMP GAUGE READING THEN CHECK VOLTAGE AT BATTERY AND FOUND THE CHARGING SYSTEM OVERCHARGING AT 18.89 VOLTS AT IDLE AND OVERCHARGING THE BATTERY WILL CAUSE THE BATTERY TO FAIL. NEED TO REPLACE THE VOLTAGE REGULATOR AND RECHECK CHARGING SYSTEM .		\$0.00	LABOR
LABOR: grs	REPLACE VOLTAGE REGULATOR DUE TO OVERCHARGING. INSTALL NEW VOLTAGE REGULATOR AND CONFIRM CHARGING SYSTEM ISN'T OVERCHARGING . THE VOLTAGE OUTPUT AT IDLE AND CRUISE IS 14.44 VOLTS. TEST DRIVE VEHICLE AND STILL HAVE SMOKE OUT OF THE EXHAUST PIPE DRIVER SIDE AND HAVE INTERMITTENT TAPPING NOISE FROM DRIVER SIDE VALVE COVER DUE TO CAMSHAFT GOING FLAT .		\$225.00	LABOR
LABOR: kjv	PERFORM ROAD TEST AFTER REPAIRS. FOUND ENGINE IS QUITTER & RUNS MUCH SMOOTHER. ENGINE PERFORMANCE IS FLAT ON ACCEL FROM A STOP. ENGINE REVS THROUGH THE GEARS BUT DOES SURGE AT ON ACCEL AT SPEEDS. PERFORMANCE IS IMPROVED BUT INTERNAL ENGINE REPAIRS WILL BE REQUIRED FOR BEST PERFORMANCE. THE EXHAUST VALVE AT #6 CYLINDER IS CAUSING AIR TO GO BACK INTO THE INTAKE MANIFOLD CAUSE LOW		\$0.00	LABOR

Warranty: From the date of delivery for a period of 6 months or 6,000 miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of \$25 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Labor/Jobs	\$3,507.30
	Parts	\$728.62
	Sublet	\$0.00
	Total Fees	\$41.75
	Subtotal	\$4,255.68
	Tax @ 9.75%	\$63.74
	Total	\$4,277.67
	Payments	\$4,341.41
	Balance	-\$63.74

Replaced parts may be requested by customer prior to vehicle pickup. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond our control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I acknowledge notice and oral approval of an increase in the original estimated price. I have read the above and acknowledge receipt of an estimate. CREDIT CARD CUSTOMERS: Cardmember agrees to perform the obligations set forth by the cardmember's agreement with the Issuer.

X _____ Date 1/14/2025

Orinda Classic Car center
 63 ORINDA WAY
 ORINDA, CA. 94563
 (925) 254-5454
 Writer: VP

INVOICE # 5047175

Service@orindaclassiccarcenter.com
 WWW.OCCC.SHOP
 BAR# BAR/ARD191519
 EPA# CAL0050068

MIKE CHAMORRO	YEAR::	1965	TRANS:/DRIVE::	MANUAL/
44 STARK KNOLL PLACE OAKLAND, CA. 94618	MAKE:/MODEL::	CHEVROLET CORVAIR CORS	LICENSE:/STATE::	NKV909/
Home: (415) 310-2482 Cell: 510	VIN::	107675L122527	MILES IN/MILES OUT:	41113/
Work: 510	ENGINE:	164 CID		

In: 9/16/2020 Out: 9/16/2020 Email: MIDDLECHAMORRO@ME.COM

ENGINE VACUUM STARVING THE OTHER TWO CYLINDERS FOR FUEL . BEST TO PERFORM ENGINE REPAIRS FIRST THEN CHECK DRIVABILITY. MAY NEED CARB ADJUSTMENT OR REBUILD.				
Total for "ACTIVE EXHAUST LEAKS AT MANIFOLD": \$1,528.56				
VEHICLE ISSUE #17: (CUSTOMER DECLINED)				
TECH REPORT: PERFORM STEERING LINKAGE REPAIRS.				
*** CUSTOMER DECLINED THIS REPAIR AT THIS TIME ***				
Total for "": \$0.00				
VEHICLE ISSUE #18: ACTIVE LEAKAGE AT BOTH FRONT WHEEL CYLINDERS.				
TECH REPORT:				
PART: 8705S	WHEEL SEAL FRONT INNER	2 @ \$7.45	\$14.90	NEW
PART: MMFWC	FRONT WHEEL CYLINDERS	2 @ \$130.00	\$260.00	NEW
LABOR: gpc	REPLACE BOTH FRONT WHEEL CYLINDERS, BLEED BRAKE SYSTEM, CLEAN AND INSPECT FRONT WHEEL BEARINGS, REPACK IF OK, REPLACE FRONT GREASE SEALS.		\$825.00	LABOR
Total for "ACTIVE LEAKAGE AT BOTH FRONT WHEEL CYLINDERS.": \$1,099.90				
VEHICLE ISSUE #19: LUBE, OIL & FILTER SERVICE -USE O/S OIL & FILTER IN TRUNK				
TECH REPORT:				
LABOR: gpc	PERFORM CHASSIS LUBRICATON AS REQUIRED, ENGINE OIL CHANGE AND OIL FILTER REPLACEMENT.		\$100.00	LABOR
Total for "LUBE, OIL & FILTER SERVICE -USE O/S OIL & FILTER IN TRUNK": \$100.00				
VEHICLE ISSUE #20: PERFORM MAINTENANCE INSPECTION - CLASSIC				
TECH REPORT:				
LABOR: gpc	PERFORM MAINTENANCE INSPECTION		\$500.00	LABOR
LABOR: gpc	LUBRICATE DOOR AND HOOD HINGES AND LOCKS		\$0.00	LABOR
Total for "PERFORM MAINTENANCE INSPECTION - CLASSIC": \$500.00				
Payment Rec'd	Credit Card Visa	Date : 10/30/2020	\$4,341.41	
9/16/2020 07:51 - VP	PHONE, INITIAL CONTACT \$602.60, 602.6			
9/18/2020 14:54 - VP	PHONE, JUST TOUCHING BASE AND STILL WORKING ON ESTIMATE, WILL CALL HIM NEXT WEEK., 0			
9/21/2020 13:41 - VP	PHONE, SPOKE TO MIKE, GAVE ESTIMATE FOR NEEDED REPAIRS, HE WILL CALL ME BACK LATER., 0			
9/21/2020 14:09 - VP	PHONE, UPDATE TO PERFORM CYLINDER LEAK DOWN TEST FOR ENGINE SMOKING, 375			

Warranty: From the date of delivery for a period of 6 months or 6,000 miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of \$25 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Labor/Jobs	\$3,507.30
	Parts	\$728.62
	Sublet	\$0.00
	Total Fees	\$41.75
	Subtotal	\$4,255.68
	Tax @ 9.75%	\$63.74
	Total	\$4,277.67
	Payments	\$4,341.41
	Balance	-\$63.74

Replaced parts may be requested by customer prior to vehicle pickup. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond our control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I acknowledge notice and oral approval of an increase in the original estimated price. I have read the above and acknowledge receipt of an estimate. CREDIT CARD CUSTOMERS: Cardmember agrees to perform the obligations set forth by the cardmember's agreement with the Issuer.

X _____ Date 1/14/2025

Orinda Classic Car center
 63 ORINDA WAY
 ORINDA, CA. 94563
 (925) 254-5454
 Writer: VP

INVOICE # 5047175

Service@orindaclassiccarcenter.com
 WWW.OCCC.SHOP
 BAR# BAR/ARD191519
 EPA# CAL0050068

MIKE CHAMORRO	YEAR::	1965	TRANS:/DRIVE::	MANUAL/
44 STARK KNOLL PLACE OAKLAND, CA. 94618	MAKE:/MODEL::	CHEVROLET CORVAIR CORS	LICENSE:/STATE::	NKV909/
Home: (415) 310-2482 Cell: 510	VIN::	107675L122527	MILES IN/MILES OUT:	41113/
Work: 510	ENGINE:	164 CID		

In: 9/16/2020 Out: 9/16/2020 Email: MIDDLECHAMORRO@ME.COM

9/28/2020 15:00 - VP	PHONE, SPOKE TO CUSTOMER FOR BATTERY REPLACEMENT AND HELI COIL REPAIR, 486.74
9/30/2020 09:59 - VP	EMAIL, AUTHORIZED, BRAKE REPAIRS, BELT REPAIR, AND EXHAUST REPAIR, 2447.31
10/28/2020 12:29 - VP	PHONE, AUTHORIZED VOLTAGE REGULATOR, OIL CHANGE, PUSHROD, VALVE COVER GASKET, 431.55

Warranty: From the date of delivery for a period of 6 months or 6,000 miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of \$25 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Labor/Jobs	\$3,507.30
	Parts	\$728.62
	Sublet	\$0.00
	Total Fees	\$41.75
	Subtotal	\$4,255.68
	Tax @ 9.75%	\$63.74
	Total	\$4,277.67
	Payments	\$4,341.41
	Balance	-\$63.74

Replaced parts may be requested by customer prior to vehicle pickup. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond our control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I acknowledge notice and oral approval of an increase in the original estimated price. I have read the above and acknowledge receipt of an estimate. CREDIT CARD CUSTOMERS: Cardmember agrees to perform the obligations set forth by the cardmember's agreement with the Issuer.

X _____ Date 1/14/2025

The end.

